

## **Technical Bulletin**

Cinch straps no longer provided with Torrentula buckets

Date:	July 11, 2013
	Bambi Bucket
Models:	Torrentula Bucket (all sizes)
Subject:	Cinch straps no longer provided with Torrentula buckets
Reference:	http://www.sei-ind.com/products/torrentula-bucket

## Details

SEI Industries will no longer install cinch straps on new Torrentula Valve Bambi Buckets.

The cinch straps on standard Bambi Buckets function to reduce the water load in the bucket by restricting the expanded volume of the bucket. Torrentula equipped buckets are able to shed extra load by opening the valve, making the cinch straps obsolete.

Removing the cinch straps will reduce weight and eliminate a possible catch point.



SEI INDUSTRIES LTD. 7400 Wilson Avenue, Delta, B.C. Canada V4G 1H3 Tel: (604) 946-3131 Fax: (604) 940-9566 E-Mail: <u>seisales@sei-ind.com</u> Web: www.sei-ind.com