

Jan. 29, 2004

**PRODUCT: TRIPPLINES**
**APPLICATION: ALL STANDARD VALVE BAMBI BUCKET MODELS**
**PURPOSE: PRODUCT INFORMATION REGARDING NEW TRIPPLINE DESIGN**
**Applicable Tripline Part Numbers:** Models 6072, 8096, 9011, 1012, 1214, 1518, 1821 - BB380


Models 2024, 2732, 3542, 4453 - BB386

Models 5566, 5870, 6578, 7590 - BB387

Models HL5000, HL7600, HL9800 - BB390

**Important:** Tripline Part no. BB385 is now obsolete and inactive, use BB386 or BB387

**OVERVIEW:** As of January 2004, SEI industries will supply Tripplines that conform to a new improved design specification. The new Tripplines are fully retrofittable replacements for the old design, and do not require any additional parts for installation. The improvements are focused on improving the durability of the catch bullet stack and cable immediately below the lower swage.



New tripline installed in Control Head. Lug Plates installed. **Note:** Control Heads built after January 2004 will not require Lug Plates.

Page 1 of 1