

Technical Bulletin

Date: November 21, 2014

Product Line: Bambi

Models: All Bambi Max Models

Subject: New Bottom Seal Clamps

Background

Bambi Max bottom seals are held to the valve tube using hose clamps. SEI has recognized that the clamps specified in the original design may come apart if the bottom seal is pulled off the valve tube.

Solution

SEI will now use two gear clamps to hold the bottom seal to the valve tube. These gear clamps will not come apart if the bottom seal is forced off the valve tube.

16" Max valves (1518-3542) will use 2x **011522** (CLAMP,GEAR,8",SS) per valve.

25" Max valves (4453-7590) will use 2x **011527** (CLAMP,GEAR,12-1/2",SS) per valve.

Please note that the original clamps do not have any detrimental impact on bucket performance.

